

Exhibit 1

12475	CN	3/17/03	Letter (attached to claim form)	Letter from City of Vancouver to Speights & Runyan re: construction date of building	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	2/09/89	Report	Hazard Assessment Survey by Pinchin-Harris and Associates	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	Undated	Report	Hazard Assessment of Asbestos Containing Materials prepared by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/12/95	Report	Asbestos Control Program	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/03/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/04/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/05/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/06/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/10/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/11/95	Report	Air Monitoring Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	5/16/96	Report	Bulk Sample Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	10/30/92	Report	Bulk Sample Results by ACM Services	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	Undated	Report	Hazard Assessment Survey Conducted by Pinchin Harris Holland	100 Oak Street Hampton, SC	Speights & Runyan
12475	CN	7/31/91	Report	Asbestos Hazard Re-Survey	100 Oak Street Hampton, SC	Speights & Runyan